

Smith Clove Elementary School - Water Testing - June 7, 2021

Room	Source	Result	Remediation
Custodial Office	Bathroom Sink	20.7 µg/L	Posted: "Do Not Drink"
OCC/Physical Therapy	Classroom Sink	57.7 µg/L	Posted: "Do Not Drink"
Second Floor Boys Room	Bathroom Sink #2	16.7 µg/L	Posted: "Do Not Drink"
Room 209	Classroom Sink	42.9 µg/L	Posted: "Do Not Drink"
Room 211	Water Fountain/Bubbler	21.5 µg/L	Posted: "Do Not Drink"
Kitchen	Kitchen Sink #1	32.5 µg/L	Posted: "Do Not Drink"
Room 213	Classroom Sink	73.1 µg/L	Posted: "Do Not Drink"
Room 214	Classroom Sink	17.5 µg/L	Posted: "Do Not Drink"
Room 210	Classroom Sink	15.6 µg/L	Posted: "Do Not Drink"
Room 210	Water Fountain/Bubbler	15.3 µg/L	Posted: "Do Not Drink"
Room 208	Water Fountain/Bubbler	16.7 µg/L	Posted: "Do Not Drink"
Room 205	Water Fountain/Bubbler	17.1 µg/L	Posted: "Do Not Drink"
Room 206	Classroom Sink	19.4 µg/L	Posted: "Do Not Drink"
Room 204	Classroom Sink	21.4 µg/L	Posted: "Do Not Drink"
Room 204	Water Fountain/Bubbler	47.2 µg/L	Posted: "Do Not Drink"
Room 203	Classroom Sink	42.8 µg/L	Posted: "Do Not Drink"
Room 004	Classroom Sink	24.7 µg/L	Posted: "Do Not Drink"
ESO	Classroom Sink	33.8 µg/L	Posted: "Do Not Drink"
Lower Level Boys Room	Bathroom Sink #3	36.6 µg/L	Posted: "Do Not Drink"
Lower Level Boys Room	Bathroom Sink #2	68.7 µg/L	Posted: "Do Not Drink"
Room 113	Classroom Sink	16.8 µg/L	Posted: "Do Not Drink"
Room 109	Water Fountain/Bubbler	348 µg/L	Posted: "Do Not Drink"
Room 110	Classroom Sink	61.6 µg/L	Posted: "Do Not Drink"